

GNÚPVERJAVIRKJUN

GEOLOGICAL REPORT

by

Sveinn Þorgrímsson

June 1973

GNÚPVERJAVIRKJUN

GEOLOGICAL REPORT

by

Sveinn Þorgrímsson

June 1973

TABLE OF CONTENTS

	<u>Page</u>
TABLE OF CONTENTS	I
LIST OF TABLES	I
LIST OF EXHIBITS	II
CHAPTER 1 Introduction	1
- 2 Geography	3
- 3 Stratigraphy	4
- 4 Superficial deposits	11
- 5 Tectonics	14
- 6 Inclination of strata	16
- 7 Groundwater	17
- 8 Engineering Geology	19

LIST OF TABLES

TABLE 1	Location and depth of drillholes.	
- 2	Direction of fractures, also presented on Rose Diagrams, Exh. 12.	
- 3	Location and depth of borro-soundings.	

LIST OF EXHIBITS

0	Note on cone, permeability and groundwater
1	Location map
2	Polanity epochs
3	Location map of drillholes, borro-soundings etc.
4	Geological map
5	Rock unit correlation map
6	" " " "
7	Graphic cone log GS-2
8	" " " GS-9
9	" " " GS-10
10	Correlation between geological sections
11	Map of superficial deposits
12	Fracture Rose diagrams
13	Geological map
14	Geological section Þjórsá - GS-9
15	Canal, Longitudinal section
16	Geological section O - O
17	" " P - P
18	" " Q - Q
19	" " R - R
20	" " S - S
21	" " T - T
22	" " U - U
23	" " V - V
24	" " X - X
25	" " Y - Y